

## City of Anaheim Industrial / Commercial Facility Inspection Form

Date:															
Reason For Inspection   Initial   Routine   Follow-up   PNIR Follow-up    I. SITE AND GENERAL INFORMATION Facility Name: Allied Pacific Metal Stamping   Contact Name: Jon Schroever   Site Address: 2951   E   La Palma Ave   Contact's Number: (714) 630-8145   Business Phone: SIC Code: 3469   NAICS Code Correction:															
Describe primary business activity: Metal Stampings,															
Facility Type: Industrial General Industrial Stormwater Permit? If Yes. 8 301005606  Does facility have a valid Business License? If Yes, Business License No: BUS1998-00189 No/Expired															
II. ACTIVITIES / BMP ASSESSMENT															
Photos Yes No Number of Photos: 6								Site	May Re	quire	Gener	al Per	mit		
Activities - Check each activity present at the site.								BMP Implementation Effectiveness Very Poor Excellent							
Vehicle or Equipment Fueling							3	rcs N	lo-	N/A	4	3	2	1	
<ol> <li>Is fueling area designed to prevent run-on of stormwater and the runoff of spills?</li> </ol>							}	<b>Y</b>						Y	
2. Are employees trained in proper fueling, cleanup, and spill response procedures?							1	Y	4	Н	H		H	X	
Are absorbent materials readily available for small spills?     Is fueling area inspected regularly for spills and/or leaks?								XXX	$\exists$	Н				V	
☐ Veh	icle or Equipment Was	shing/Steam Clea	ning												
	Ignated wash area used?							_		X	8	188		袋	
Is wash area equipped with clarifier and connected to sanitary sewer?     Is designated wash area designed with complete containment?								-	-	×	壁	50			
	rifier or oil/water separat			e document	ed?			<b>=</b>		V		173	32	建	
Veh	icle or Equipment Mai	intenance and Re	peir									~			
	intenance performed in d	-						Y.	4	Н	$\mathbb{H}$	Н	H	¥	
Is equipment kept clean, no build-up of cil and grease?     Arc drip pans and containers used in areas where drips or leaks may occur?									┥	H	H	H	H	7	
	sed oil and oil filters, and			·			Ì	Ž						V	
Out	door Londing/Uniondi	ng of Materials												_	
	elivery vehicles purked s	•					ļ	<b>Z</b>		$\Box$				Z	
2. Is the loading/unloading dock/area covered to reduce exposure of materials to rain?  3. Is loading/unloading dock/area decisioned to restorm stormwater run.co.2.						}	$\dashv$ $\mid$	Y	Н	#3 %#	<b>133</b>	編	<b>EX</b>		
3. Is loading/unleading dock/area designed to prevent stormwater run-on?  4. Are forklift operators properly trained to use heavy equipment?							7	*	Н	338		ñ	<b>₹</b>		
	interials loaded near Stor		• • •				l		V		露	选	海	<b>2</b>	
_	door Storage of Mater	-	ufpment												
1. Are covers used to protect items stored outside?  (Check covering type used)  Plastic  Roof  Canopy  Other								✓						Y	
		_		_	_	Ouki	1		$\neg$					П	
Are materials/products on pallets or other structures that keep them off the ground?     Are spill containment pallets used?							Ž	╛				Ĭ	$\mathbf{V}$		
4. Are b	erns, curbs, or other stru	actures in place to	minimize pollutants fi	mm entering	the stranswate	er streams?		<b>y</b>	Ш						
<b>₩</b> was	ste Handling and Dispo	peal													
	nterials recycled whene							Y						Z	
Are dust and particulates properly managed (indoors and outdoors)?     Are wastes segregated and seperated?								$\dashv$	H	$\mathbb{H}$	H	M			
	rage area designed to pre		unoEl?						_	H	Н	H	7		
	raste dumpsters covered?								Z		經	153	122		
_	ding and Grounds Ma								_			(ET)	FREE		
_	esticides and fertilizers t eas swept regularly?	asea ana storea pro	peny:					7	-	<b>Y</b>	35	444	- 14/3 - 14/3	77	
	shdown by hosing prohib	oited?					į	Z						Z	
4. Are wash water, sweeping, and sediments disposed properly?							<b>Y</b>	_			apt.	52	Y		
<ol> <li>Are materials used in repair and minor remodeling (paints, etc.) stored properly?</li> <li>Are paved surfaces adequately maintained (no crumbling asphalt or concrete)?</li> </ol>							7	$\dashv$		85	盘	F38	KIRK		
	dible Surface Areas	,													
Are areas of exposed/disturbed soil properly managed?							1			¥	74	13. 13.	92	13	
2. Do any landscaped areas require re-vegetation?								Z		2	25	<b>3</b>	133		
Em <sub>i</sub>	ployee Stormwater Ma	ungement Traini	ng			-						_	_	_	
	ployees receive general		-		elle /D\m !	damentari		<b>Y</b>	Н	Н	11-1	Н	$\vdash$	Y	
	ployees receive training aining records and educ			TOTAL TROUB	i ette (13ML 10)	жения (ICD) <i>(</i>			H	Н	$\mathbb{H}$	Н	Н		

- 1 All necessary BMPs used and very effective 3 Some BMPS used but not effective



## City of Anaheim Industrial / Commercial Facility Inspection Form

## II. ACTIVITIES / BMP ASSESSMENT:

Observations/Comments:										
At the time of inspection, I observed the trash can lids were open, Mr. Cecil indicated he keeps the lids closed as much as practicable. It is recommended the waste dumpster be covered at all times to protect waste from being discharged due to winds/rain to reduce potential for pollutants to be mobilized in storm water discharge.										
Observed thirt, dust, and leaves accumulated under the rear covered storage area. Also, observed small amounts of sediment in the swale in the rear yard area.  Recommended an increase sweeping regime for the area to reduce potential pollutant sources.										
Based on conversation with the site representative and observations at time of inspection, aside from the above items. BMPs currently in place appear effective and good housekeeping BMPs appeared implemented. Facility is kept clean and well maintained.										
The inspection revealed no evidence of illegal discharge.										
Corrective Action:										
Due Date:										
er e										
III. Prioritization Verification										
Outdoor Activity - Percent of activities outdoors and uncovered: 0% & <0 - 25% 25 - 75% >75%										
Discharge Potential - (BMP Assessment) Fully Implemented Partially Implemented										
Non-Stormwater Discharges: None observed / no evidence of / no sources noted Sources observed, but BMPs in place										
Sources observed, insufficient BMPs in place, but no discharge or evidence of a discharge or evidence of a discharge insufficient BMPs										
Facility Size - Approx. impervious area										
Material Used - Material(s) kept indoors or properly covered outdoors:   Most Some Few/None										
Waste Generated Wastes properly disposed and managed Wastes not disposed and/or managed properly										
IV. Violation(s) of City Ordinance (Chapter 10.09)										
No violations noted during inspection/investigation Illegal discharge(s) of pollutants Illegal connection										
Other										
Any spill/discharge that poses immediate significant threat to receiving waters or requires hazardous materials response?										
If this is a follow-up inspection, was compliance obtained?										
V. Corrective Actions										
Corrective Actions   None   Correct deficiencies noted above in time frame indicated   Facility BMP Information Provided										
Follow-up Inspection Required? Yes Inspection to be performed after: No										